Suyash Education Society

President / Secretary / Treasurer

## PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE.

No. 615	Date : 21 10 2024
40	
It is certified that an inspection	team headed by Ridam Shall
Sub-Engin	(Name of Officers
with designation) from Pable H Department/Office) inspected the	Angels Planet School
Harsud Road-Khundwa	
	found that the Angles Planet School
	(Name of school) has safe
drinking water facilities for the students and	members of staff of the institution and is maintaining
prescribed by the Central/State/U.T Govt.  The above valid for a period of	Signature with Seal:  Name  ANUPAM GAHOF  Designation  Signature & Compus as per the norms  ANUPAM GAHOF
10	
Principal,	
Angels Planet School Marsuel Road-Khandwa	
Name & Address of the Institution)	

ANGELS PLANET SCHOOL

CBSE No. 1030709

Vill. Bhandariya, Harsud Road

KHANDWA (M.P.)

## कार्यालय सहायक यंत्री,लोक स्वास्थ्य यांत्रिकी उपखण्ड - खण्डवा

क्रमांक 338./प्रयोगशाला/सयं/लोखायां/2024

खण्डवा दिनांक 12/09/24

प्रति,

प्राचार्य एंजल प्लेनेट स्कूल भंडारिया खण्डवा

विषय:- पेयजल नमूनों की परीक्षण रिपोर्ट बाबत्।

संदर्भ :- आपका पत्र क्र.- निरंक / दिनांक - 10.09.2024

---00---

उपरोक्त विषयान्तर्गत लेख हैं कि आपके संदर्भित पत्र के साथ प्रेषित जल नमूने का परीक्षण उपरांत परीक्षण रिपोर्ट पत्र के साथ संलग्न कर आपकी ओर प्रेषित की जा रही है।

संलग्न - 01 जल नमूने की रासायनिक/भौतिक एवं जीवाणु परीक्षण रिपोर्ट।

संहायक यंत्री लोक स्वास्थ्य यांत्रिकी उपखंड खंडवा म.प्र

URN No. MPTURN100920240003124 dt-10.09.2024 Amt 1550/-Chemical/Physical & Bacteriological water Sample Testing charges

PRINCIPAL
ANGELS PLANET SCHOOL
CBSE No. 1030709
Vill. Bhandariya, Harsud Road
KHANDWA (M.P.)

Suyash Education Society

President / Secretary Treasurer

## // WATER ANALYSIS REPORT //

## WATER TESTING LABORATORY, PUBLIC HEALTH ENGINEERING SUB DIVISION KHANDWA

Lab Report No:- 338. DWTL/PHE/KHANDWA

Date :- 12 09 24

1. Particulars of Sender:

Principal

**Angel Planet School** 

Bhandariya Khandwa

3.Senders Letter NO: - - Date :- 10.09.2024

4.URN No. MPTURN100920240003124 Date: 10.09.2024

5.Date of sample Receipt :- 10.09.2024

6.Date of Testing :- 10.09.2024

2.Particulars of Sample:

Place Where sample is collected -

01. Angel Planet School

Bhandariya Khandwa

Source - R.O. water sample

			Appendix 23(a) as per manual on Water Supply Treatment prepared published by BIS Standard:IS 10500:2012  8.Water Sample not Collected by Lab RESULT OBTAINI		A CONTRACTOR OF THE CONTRACTOR
	Characteristics				RESULT OBTAINED
S.No		Linita			
		Units	Requirment	Permissible	
		1	(Desirable	Limit in the	
			Limit)	Absence of	
				Alternate	
_				Source	Sample No 01
1	2	3	4	5 .	6
- 1	Troub! dia .		PHYSICAL - TE		
	Turbidity	NTU	1	5	1.8
2	Colour	Hazen	5	15	-
	Tou:	T	CHEMICAL - TI		
-	PH	pH Scale	6.5 to 8.5	No relaxation	7.81
	TDS	Mg/L	500	2000	537
	Chlorides	Mg/L	250	1000	94
	Nitrates	Mg/L	45	45	
	Total Hardness (as caco3)	Mg/L	200	600	340
8	Calcium	Mg/L	. 75	200	71
9	Magnesium	Mg/L	. 30	100	39
10	Total Alkalinity (as CaCO3)	Mg/L	200	600	257
11	Iron (as Fe)	Mg/L	1.0	1.0	0.1
12	Fluoride (as F)	Mg/L	1.0	1.5	0.15
13	Sulphate (as SO4)	Mg/L	200	400	10
14	Residual Chlorine	PPM	0.2	1	
		BAG	TERIOLOGICAL	- TEST	
15	Faecal Coliform	per/ 100 ml	4	Nill	Nill

Remark: -Please disinfection of drinking water is necessary with bleaching powder or sodium hypochloride before using .

NOTE :- The figurers indicated under column "Desirable Limit" in table given above limits up to which the water is generally acceptable to the consumer.

The figures is exces of those mentioned under "Permissible Limit" render the water acceptable but still may be tolerated in the absence of alternative and better source bellow the limits indicated under column "Permissible Limit" above, beyond which the supply have to be rejected.

Vill. Bhandariya, Harsud Road KHANDWA (M.P.)

LABORATORY INCHARGE

ASSISTANT ENGINEER PHE SUB DIVISION KHANDWA